


## Diagnosis Temperature-Pressure

<b>Compressor type</b>	<b>Variable Displacement ( internally contr'd)</b>
<b>Expansion Device</b>	<b>Expansion Valve</b>
<b>Pressure High Side</b>	<b>Too high ( see gauge)</b>
<b>Pressure Low Side</b>	<b>Too low ( see gauge)</b>
<b>Temperature suction line</b>	<b>Not cold</b>
<b>Complaint</b>	<b>No cooling</b>



### Possible causes:

- **Temporary blockages on the high pressure side (e.g. dryer, expansion valve)**

**Remarks: Vibrating hand on high side gauge**